


Stratus Gen 1 ERP25/252 Compressor Rebuild Kit



If your air compressor runs but does not pump air after a couple years of service, chances are the Teflon® Piston Ring(s) needs to be replaced. Our rebuild kits will get your air compressor running like new.

Rating: Not Rated Yet

Price

\$75.00

[Ask a question about this product](#)

Description

ERP Compressor Rebuild Kits

Includes piston ring, gaskets, seals and leaf valves